

repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fatigue cracking in the lower spar cap of the wing rear spar and in the lower skin at the wing front spar, just outside the nacelle, on the left-hand and right-hand side of the airplane, which could result in fuel leakage and consequent fire in or around the wing, accomplish the following:

(a) Prior to the accumulation of 13,000 total flight cycles, or within 500 flight cycles after the effective date of this AD, whichever occurs later, modify the airplane by coldworking the fastener holes at the front and rear wing spar (including all applicable nondestructive test and detailed visual inspections and repairs of holes) and installing modified support angles for the lower trailing edge panel of the wing, in accordance with the instructions of Saab Service Bulletin SAAB 2000-57-029, dated June 4, 1999.

(b) Where Saab Service Bulletin 2000-57-029, dated June 4, 1999, specifies that Saab be contacted for repair instructions for certain damage conditions, this AD requires that such damage conditions must be repaired in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate; or the Luftfartsverket (LFV) (or its delegated agent). For a repair method to be approved by the Manager, International Branch, ANM-116, as required by this paragraph, the Manager's approval letter must specifically reference this AD.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in Swedish airworthiness directive SAD 1-142, dated June 4, 1999.

Issued in Renton, Washington, on September 17, 1999.

D.L. Rigglin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 99-24848 Filed 9-22-99; 8:45 am]

BILLING CODE 4910-13-P

PRESIDIO TRUST

36 CFR Part 1010

RIN 3212-AA02

Management of the Presidio: Environmental Quality

AGENCY: The Presidio Trust.

ACTION: Extension of public comment period.

SUMMARY: This action extends until October 5, 1999 the period for public comment on the proposed rule published in the **Federal Register** (64 FR 39951-39963) on July 23, 1999 (proposed 36 CFR Part 1010). This proposed rule would implement the National Environmental Policy Act (NEPA) and replace the Presidio Trust's interim procedures and guidelines implementing NEPA, the availability of which was noticed in the **Federal Register** on September 14, 1998 (63 FR 49142).

DATES: Comments on the proposed rule must be received by October 5, 1999.

ADDRESSES: Written comments on the proposed rule must be sent to Karen A. Cook, General Counsel, Presidio Trust, 34 Graham Street, P.O. Box 29052, San Francisco, CA 94129-0052.

FOR FURTHER INFORMATION CONTACT: Karen A. Cook, General Counsel, Presidio Trust, 34 Graham Street, P.O. Box 29052, San Francisco, CA 94129-0052. Telephone: 415-561-5300.

Dated: September 17, 1999.

Karen A. Cook,

General Counsel.
[FR Doc. 99-24785 Filed 9-22-99; 8:45 am]
BILLING CODE 4310-4R-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[MD069-3031b and MD070-3031b; FRL-6440-7]

Approval and Promulgation of Air Quality Implementation Plans; Maryland; Control of Volatile Organic Compounds From Vinegar Generators and Leather Coating Operations

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: EPA proposes to approve the State Implementation Plan (SIP) revision submitted by the State of Maryland for the purpose of establishing volatile organic compound control requirements on vinegar generators and leather coating operations. In the Final Rules section of this **Federal Register**, EPA is approving the State's SIP submittal as a direct final rule without prior proposal because the Agency views this as a noncontroversial submittal and anticipates no adverse comments. A more detailed description of the state submittal and EPA's evaluation are included in a Technical Support Document (TSD) prepared in support of this rulemaking action. A copy of the TSD is available, upon request, from the EPA Regional Office listed in the **ADDRESSES** section of this document. If no adverse comments are received in response to this action, no further activity is contemplated. If EPA receives adverse comments, the direct final rule will be withdrawn and all public comments received will be addressed in a subsequent final rule based on this proposed rule. EPA will not institute a second comment period on this action. Any parties interested in commenting on this action should do so at this time.

DATES: Comments must be received in writing by October 25, 1999.

ADDRESSES: Written comments should be addressed to Kathleen Henry, Chief, Permits and Technical Assessment Branch, Mailcode 3AP11, U.S. Environmental Protection Agency, Region III, 1650 Arch Street, Philadelphia, Pennsylvania 19103. Copies of the documents relevant to this action are available for public inspection during normal business hours at the Air Protection Division, U.S. Environmental Protection Agency, Region III, 1650 Arch Street, Philadelphia, Pennsylvania 19103; the Maryland Department of the Environment, 2500 Broening Highway, Baltimore, Maryland, 21224.